
241 9,361 59,500+

Update projects / houses / people




to improve living conditions

2019 - the % of 9,085 houses functioning *before* fix work:

Electrically safe

A working shower

A working kitchen




2019 - the % of 9,085 houses functioning *after* fix work:

Electrically safe

A working shower

A working kitchen



by the residents

Faulty? poor construction

Routine? normal wear

287,919+ items fixed or inspected